



# Inspection Report

Inspection Date: 2024/07/30

## Generator

### General Information

<b>Maker</b>	DENYO
<b>Model Number</b>	DCA-25ESI2
<b>Year</b>	
<b>Hour (h)</b>	10183
<b>Serial Number</b>	3843965

### Note for External Appearance

- Repainted

### Engine

<b>Model</b>	AA-4LE2
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

### Note for Engine

Admin. No. 3000063160

\*This report is only for your reference. We are not responsible for the actual condition of checked item.