



Inspection Report

Inspection Date: 2023/01/26

Excavators

General Information

Maker	KOMATSU		
Model Number	PC30MR-5		
Year	2019		
Hour (h)	610	Meter	Working
Serial Number	KMTPC262HKE055653		

Options

- Blade	- Speed changer
- EPA	- Pippings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	700			

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- Without standard bucket
- With slope bucket



Note for Undercarriage

- The hydraulic power of left shoe is weak



Engine

Model	3D88E-7ESDA
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000045377