



Inspection Report

Inspection Date: 2024/08/08

Wheel Loader

General Information

Maker	CAT
Model Number	901B
Year	2005
Hour (h)	2176
Serial Number	W7A00882

Note for External Appearance

- Repainted
- The corner of the lower cabin has been repaired



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

- With CAB (cabin) heater



Engine

Model	K3M-E4DT
Serial Number	K3M-28071
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 3000062446

*This report is only for your reference. We are not responsible for the actual condition of checked item.