



Inspection Report

Inspection Date: 2021/05/06

Wheel Loader

General Information

Maker	FURUKAWA
Model Number	FL302-3
Year	2002
Hour (h)	1813
Serial Number	F36-01616

Note for External Appearance

- The body is partly damaged and rusty



Upper Structure

Lift Arm Cylinder (Left)	Oil oozing
Lift Arm Cylinder (Right)	N/A
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component



Engine

Model	D1503
Serial Number	01W0533
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- The undercarriage is partly damaged and rusty



Documents

Automobile Inspection Certificate	No
-----------------------------------	----

Note for Engine



Admin. No. 3000031319

*This report is only for your reference. We are not responsible for the actual condition of checked item.