



Inspection Report

Inspection Date: 2021/11/19

Excavators

General Information

Maker	KOMATSU		
Model Number	PC28UU-3		
Year	2006		
Hour (h)	5750	Meter	Working
Serial Number	KMTPC013C05032233		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	425			

Note for External Appearance

The horizontal acrylic plate of the canopy is broken



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

The standard bucket, clamp, and thin bucket are attached



Note for Undercarriage



Engine

Model	3D82AE-3HB
Serial Number	18435
Engine Oil Leak	Oil leak
Engine Oil Gauge	OK
Radiator	Rust/Oil
Exhaust Color	Normal
Blow-by	No
Engine Sound	NG
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

The engine has abnormal noise and vibration



Admin No. 3000036477