



# Inspection Report

Inspection Date: 2024/11/29

## Excavators

### General Information

|                      |            |              |         |
|----------------------|------------|--------------|---------|
| <b>Maker</b>         | KOBELCO    |              |         |
| <b>Model Number</b>  | SK125SR    |              |         |
| <b>Year</b>          | 2010       |              |         |
| <b>Hour (h)</b>      | 5847       | <b>Meter</b> | Working |
| <b>Serial Number</b> | YV06-05823 |              |         |

### Options


|              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Blade      |                   |
| - Arm Crane  |                   |
| - EPA        |                   |

### Upper Structure

|                  |       | Cylinder |              | Play  |
|------------------|-------|----------|--------------|-------|
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | Small |
|                  | Right | No       | No           |       |
| Arm              |       | No       | No           | Small |
| Bucket           |       | No       | No           | Small |
| Bucket Size (mm) | 790   |          |              |       |

### Note for External Appearance

- Repainted  
 - The body has some rust, scratches, dents, and corrosion  
 - Maybe oil oozing from the bottom



### Undercarriage

|                     |                              |              |
|---------------------|------------------------------|--------------|
| <b>Shoe Type</b>    | Steel shoes with rubber pads |              |
| <b>Swing Circle</b> | No oil leak                  |              |
|                     | <b>Left</b>                  | <b>Right</b> |
| Shoe Width (mm)     | 500                          | 500          |
| Idler               | OK                           | OK           |
| Sprocket            | OK                           | OK           |
| Pin Bush            | OK                           | OK           |
| Upper Roller        | OK                           | OK           |
| Track Roller        | OK                           | OK           |
| Shoe Link           | OK                           | OK           |

### Note for Upper Structure



### Note for Undercarriage



### Engine

|                         |               |
|-------------------------|---------------|
| <b>Model</b>            |               |
| <b>Serial Number</b>    |               |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | Oil shortage  |
| <b>Radiator</b>         | OK            |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Hydraulic Pump</b>   | No oil leak   |
| <b>Water Pump</b>       | No water leak |
| <b>Oil Cooler</b>       | No oil leak   |
| <b>Motor</b>            | No oil leak   |
| <b>Multi Lever</b>      | No oil leak   |

### Note for Operating Component



### Note for Engine



Admin No. 3000066782