



# Inspection Report

Inspection Date: 2018/06/16


## Excavators

General Information			
Maker	YANMAR		
Model Number	ViO20-3		
Year	2006		
Hour (h)	4428	Meter	Working
Serial Number	33173B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		425		

Note for External Appearance
<ul style="list-style-type: none"> <li>- The body is partly painted</li> <li>- The canopy has some dents</li> <li>- The lower part of the right cover has some dents</li> </ul>




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	NG	
Shoe Link	OK	OK	

Note for Upper Structure
<ul style="list-style-type: none"> <li>- No bucket teeth</li> <li>- The boom has plays</li> </ul>




Note for Undercarriage
Oil oozing from one of the right lower rollers



Engine	
Model	3TNV76-P
Serial Number	27827
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat has been fixed



Note for Engine



Admin No. 2018060931