



Inspection Report

Inspection Date: 2018/09/18


Excavators

General Information			
Maker	HITACHI		
Model Number	ZX135US-3		
Year	2008		
Hour (h)	5886	Meter	Working
Serial Number	HCM1R400K00081636		

Options	
- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		880		

Note for External Appearance




Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure




Note for Undercarriage



Engine	
Model	4JJ1-XDJAA-01-C2
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component

- The seay is partly worn
- The seat has a cover



Note for Engine



Admin No. 2018090200