



Inspection Report

Inspection Date: 2018/09/15


Excavators

General Information			
Maker	YANMAR		
Model Number	B7-5A		
Year	2007		
Hour (h)	5035	Meter	Working
Serial Number	58289B		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		630		

Note for External Appearance




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	NG	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage
Oil oozing from the reduction drive of the right travel motor




Engine	
Model	4TNV98-XBV
Serial Number	42239
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine



Admin No. 2018090179