

ZX330LC-3 Hydraulic Shovel

BASIC INFORMATION

Inspection Date	21	Model	ZX330LC-3	Serial No.	54811
Date of Manufacture		Hourmeter	13893 HR	Condition of Hourmeter	HR is normal
Hourmeter (Estimated)		Engine No.		Job Status	Scrap
Accident History		Cabin/Canopy	Cabin	Cabin Type	Lift
Front Attachment	Standard	Super long length(m)		Type of Shoe	Flat
Width of Track Shoe	600	Bucket/Attachment	No Bucket	Stamp	Not confirmed
Others	EPA, Air Conditioner				

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Moderate/Within Service Limit	Traveling	Normal	Front Attachment	Normal
Pump Device	Normal				

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread(Right)	Moderate/Within Service Limit	Wear: Track Link Tread(Left)	Moderate/Within Service Limit	Wear: Track Link Pins (Right)	Moderate/Within Service Limit
Wear: Track Link Pins (Left)	Moderate/Within Service Limit	Wear: Track Shoe/Rubber Shoe	Moderate/Within Service Limit	Bent/Broken/Missing: Track Shoe	More than 10 Pieces
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Broken/Crack: Rubber Shoe(Right)		Broken/Crack: Rubber Shoe(Left)		Missing: Rubber Shoe Core	
Wear: Upper Rollers	Moderate/Within Service Limit	Wear: Lower Rollers	Moderate/Within Service Limit	Oil Leak: Rollers	1~4 Pieces
Broken/Missing: Rollers	1~4 Pieces	Wear: Front Idler(Right)	Moderate/Within Service Limit	Wear: Front Idler(Left)	Moderate/Within Service Limit
Wear: Sprocket(Right)	Moderate/Within Service Limit	Wear: Sprocket(Left)	Moderate/Within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Boom	Normal	Arm	Deformed/Dent	Wear: Boom Foot Pin	Moderate/Within Service Limit
Wear: Boom/Arm Joint Pin	Moderate/Within Service Limit	Wear: Arm Tip Pin		Wear: Other Pins	
Wear/Deformation: Bucket		Wear/Deformation: Blade			

OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder(Right)	No	Oil Leak: Boom Cylinder(Left)	Slight Film
Oil Leak: Arm Cylinder(Right)	Slight Film	Oil Leak: Arm Cylinder(Left)		Oil Leak: Bucket Cylinder(Right)	Slight Film
Oil Leak: Bucket Cylinder(Left)		Oil Leak: Offset Cylinder		Oil Leak: Blade Cylinder	
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	Slight Film
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	Slight Film	Oil Leak: Pilot Pipes	Moderate Oozing
Oil Leak: Pilot Valve	Moderate Oozing	Oil Leak: Center Joint	Slight Film	Oil Leak: Swing Device	No
Oil Leak: Pump Device	Moderate Oozing				

APPEARANCE

Engine Cover	Deformed/Dent	Side Covers	Deformed/Dent, Cracked, Rusted/Corroded	Under Covers	Deformed/Dent
Counter Weight	Scratched	Main frame	Good Condition	D Frame	Deformed/Dent
Track Frame	Deformed/Dent	Cabin	Deformed/Dent	Door	Good Condition

INTERIOR

Cabin Interior	Torn	Seat	Torn	Console	Faded
Air conditioner	Malfunction	Freon gas inspection	Good Condition		

OVERALL RATING

Appearance Evaluation	Poor	Rust/Corrosion	Moderate	Overall Rating	Able to Use
Special Notes	BKなし 干渉防止すぐに作動する				