



# Inspection Report

Inspection Date: 2018/10/17

## Carrier Dump

### General Information

|                      |        |
|----------------------|--------|
| <b>Maker</b>         | YANMAR |
| <b>Model Number</b>  | C12R-B |
| <b>Year</b>          | 2011   |
| <b>Hour (h)</b>      | 698    |
| <b>Serial Number</b> | 26373C |

### Note for External Appearance

### Engine

|                         |               |
|-------------------------|---------------|
| <b>Model</b>            | 2TE67L-FW3    |
| <b>Serial Number</b>    | 10539         |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | OK            |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Radiator</b>         | OK            |
| <b>Water Pump</b>       | No water leak |
| <b>Injection Pump</b>   | No fuel leak  |

### Note for Control Panel

### Note for Engine

### Other Information

Oil oozing from the sprockets

Admin. No. 2018100127

\*This report is only for your reference. We are not responsible for the actual condition of checked item.