



# Inspection Report

Inspection Date: 2017/08/08


## Excavators

General Information			
Maker	KUBOTA		
Model Number	RX-203S		
Year	2007		
Hour (h)	2956	Meter	Working
Serial Number	10401		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		400		

Note for External Appearance
- Repainted - The serial plate has come off - VIN unchecked




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The blade has dents




Note for Undercarriage
The rubber shoes have deteriorated over time and are worn



Engine	
Model	D1105
Serial Number	7S9484
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
Torn seat



Note for Engine



Admin No. 2017080019