



# Inspection Report

Inspection Date: 2023/02/10

## Roller

### General Information

<b>Maker</b>	HITACHI
<b>Model Number</b>	CP220-3
<b>Year</b>	2011
<b>Hour (h)</b>	1405
<b>Serial Number</b>	HCMUC00C00030267

### Engine

<b>Model</b>	4JJ1
<b>Serial Number</b>	123990
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for External Appearance



### Note for Undercarriage

- The side tires (both front and rear) are cracked (please check the photos)



### Note for Operating Component

- Mileage: 3,826 km



### Note for Engine

- Oil oozing from around the engine cover



Admin. No. 3000045516

\*This report is only for your reference. We are not responsible for the actual condition of checked item.