



# Inspection Report

Inspection Date: 2018/11/05

## Aerial Work Platform

### General Information

<b>Maker</b>	S-MAC
<b>Model Number</b>	PH40-3
<b>Year</b>	2006
<b>Hour (h)</b>	331
<b>Serial Number</b>	232

### Note for External Appearance

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	#N/A
<b>Engine Oil Gauge</b>	#N/A
<b>Exhaust Color</b>	#N/A
<b>Blow-by</b>	#N/A
<b>Engine Sound</b>	#N/A
<b>Radiator</b>	#N/A
<b>Water Pump</b>	#N/A
<b>Injection Pump</b>	#N/A

### Note for Control Panel

### Note for Engine

This item was inspected without starting the engine because there was not enough battery

### Other Information

Admin. No. 2018110033

\*This report is only for your reference. We are not responsible for the actual condition of checked item.