



# Inspection Report

Inspection Date: 2018/09/20


## Excavators

General Information			
Maker	KOMATSU		
Model Number	PC120-8		
Year	2014		
Hour (h)	47	Meter	Working
Serial Number	87125		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		850		

Note for External Appearance
- Unused item
- The date of manufacture: Jan. 2014



Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage



Engine	
Model	SAA4D95LE-5
Serial Number	549282
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 2018090319