



Inspection Report

Inspection Date: 2018/06/15

Excavators

General Information

Maker	YANMAR		
Model Number	ViO30-5		
Year	2006		
Hour (h)	5419	Meter	Working
Serial Number	50610B		

Options

- CNP
- Multilever
- Blade
- Speed changer

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		470		

Note for External Appearance

- The body is partly painted
- The canopy has some scratches



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	NG	OK
Sprocket	OK	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure

- The tip of the arm has some dents
- The bucket has plays



Note for Undercarriage

- The sprockets are severely worn
- The rubber shoes have deteriorated over time, are worn, and partly cracked



Engine

Model	
Serial Number	35522
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn



Note for Engine



Admin No. 2018060974