



# Inspection Report


Inspection Date: 2018/07/10

## Excavators


General Information			
Maker	KOBELCO		
Model Number	SK125SR		
Year	2010		
Hour (h)	4267	Meter	Not Working
Serial Number	YV06-05616		


Options	
- CAB	- Air conditioner
- Multilever	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	No	No	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		800		


Note for External Appearance



Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	700	700	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
Upper structure movement is unchecked


Note for Undercarriage
- One of the shoes does not work properly according to the seller
- Traveling motion is unchecked
- The shoes have some kinks


Engine	
Model	D04FR-004156
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
Engine movement is unchecked because the hydraulic pump is broken according to the seller


Admin No. 2018070052