



# Inspection Report

Inspection Date:

## Aerial Work Platform

### General Information

<b>Maker</b>	NAGANOKOGYO
<b>Model Number</b>	NUZ090D
<b>Year</b>	2006
<b>Hour (h)</b>	3119
<b>Serial Number</b>	9NZ047

### Note for External Appearance

- Repainted
- The body has some scratches, rust, and corrosion

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	Unchecked
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

### Note for Engine

### Other Information

Admin. No. 3000073791

\*This report is only for your reference. We are not responsible for the actual condition of checked item.