



Inspection Report

Inspection Date: 2022/08/19

Excavators

General Information

Maker	HITACHI		
Model Number	ZX75US-3		
Year	2013		
Hour (h)	2970	Meter	Working
Serial Number	HCM1P300L00063533		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Piping
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		Oil leak	No	Small
Bucket		No	No	Big
Bucket Size (mm)	650			

Note for External Appearance

- The body is rusty and damaged



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The bucket side cutters are missing
- The bucket side is bent



Note for Undercarriage



Engine

Model	Au-4LE2XYSA-01
Serial Number	4LE2-296595
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000042447