



Inspection Report

Inspection Date: 2026/09/02

Excavators

General Information

Maker	CAT		
Model Number	303ECR		
Year	2016		
Hour (h)	4993	Meter	Working
Serial Number	CAT0303EJSMG01519		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Pippings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		0		

Note for External Appearance

- No bucket
- The body has rust, scratches, and dents



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- It does not swing
- The arm has been reinforced



Note for Undercarriage

- Traveling is slow



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The accelerator lever is stiff



Note for Engine

- Oil oozing from the control valve



Admin No. 3000088937

*This report is only for your reference. We are not responsible for the actual condition of checked item.