



Inspection Report

Inspection Date: 2025/09/12

Truck

General Information

Maker	HINO
Model Number	BDG-XZU344M-TKMRD3
Year	2009
Mileage (km)	51951
Serial Number	XZU344-1003125

Note for External Appearance

- Aerial work platform
- MODEL: SK22-A
- S/N: 728145
- Repainted partly
- The upper structure and outriggers has rust and corrosion

Engine

Model	N04C-TK
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- 4827HR
- Instruction manual and maintenance notes included

Note for Engine

- Oil oozing from under the engine

Admin. No. 3000077184

*This report is only for your reference. We are not responsible for the actual condition of checked item.