



Inspection Report

Inspection Date: 2022/08/19

Excavators

General Information

Maker	KOMATSU		
Model Number	PC200-8N1		
Year	2007		
Hour (h)	6693	Meter	Working
Serial Number	KMTPC197K02310499		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	1000			

Note for External Appearance



Note for Upper Structure



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage



Engine

Model	SAA6D107E-1
Serial Number	26509563
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- With a rear-view camera



Note for Engine

- The battery is flat. The engine started with the booster cables.



Admin No. 3000042000