



Inspection Report

Inspection Date: 2018/12/05


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-30-5		
Year			
Hour (h)	1012	Meter	Working
Serial Number	78619		

Options	
- CNP	- Speed changer
- Blade	- Breaker Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		425		

Note for External Appearance
The left side cover and the counterweight have some scratches




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	NG	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage



Engine	
Model	
Serial Number	7ER1786
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 2018110327