



Inspection Report

Inspection Date: 2020/06/18

Roller

General Information

Maker	BOMAG
Model Number	BW211D-4
Year	2007
Hour (h)	
Serial Number	101582401050

Engine

Model	BF 4M 2012 C
Serial Number	01094500
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	Rust/Oil


Note for External Appearance

- Vibration is working properly
- The right lower part of the cabin is decayed
- The rear part of the engine hood cover is cracked



Note for Undercarriage

- The quake-absorbing rubbers have deteriorated
- Oil oozing from the steering cylinder
- Oil oozing from the left traveling motor of the front tire
- Rear tire size: 20.5-25 12PLY



Note for Operating Component

The current hour meter is 398, but it has been replaced



Note for Engine

Oil oozing from the pump



Admin. No. 3000010194

*This report is only for your reference. We are not responsible for the actual condition of checked item.