



Inspection Report

Inspection Date: 2024/08/08

Wheel Loader

General Information

Maker	YANMAR
Model Number	V3-5B
Year	2006
Hour (h)	2937
Serial Number	L3DA-53785

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Engine

Model	3TNV84-XKAH
Serial Number	30722
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	No
-----------------------------------	----

Note for External Appearance

- The bucket and counterweight are repainted



Note for Upper Structure



Note for Operating Component

- With CAB (cabin) heater
- The right side step of the cabin is corroded



Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.



Note for Engine

- EPA



Admin. No. 3000062470

*This report is only for your reference. We are not responsible for the actual condition of checked item.