



Inspection Report

Inspection Date: 2021/08/28

Excavators

General Information

Maker	SUMITOMO		
Model Number	SH75X-3B		
Year	2012		
Hour (h)	4717	Meter	Working
Serial Number	SMT075X3T00BB8181		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		725		

Note for External Appearance

- The covers have some dents



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	NG	NG
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The engine stops under pressure while idling
 - The upper part of the blade has some dents
 - 2 sides of the arm have been reinforced



Note for Undercarriage

- The left upper rollers are damaged
 - The right upper rollers are deformed



Engine

Model	AU-4LE2XYSS-01
Serial Number	4LE2-285622
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- A front window is missing



Note for Engine

- The engine cover lock has some problems



Admin No. 3000034223