Inspection Report

Inspection Date: 2026/11/12

Excavators

General Information

Maker	YANMAR		
Model Number	J09		
Year			
Hour (h)	1776	**Meter**	Working
Serial Number	01032		

Options

- Blade	- Speed changer

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	**Left**	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		330		

Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	**Right**
Shoe Width (mm)	180	180
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for External Appearance

- Repainted
- The body has scratches and rust



Note for Upper Structure

- The blade power is weak



Note for Undercarriage

- The right adjustable shoe is not responsive



Note for Operating Component



Note for Engine



Admin No. 3000091795

*This report is only for your reference. We are not responsible for the actual condition of checked item.