



Inspection Report

Inspection Date: 2020/07/04

Dozer

General Information

Maker	KOMATSU
Model Number	D31PX-22
Year	2013
Hour (h)	5818
Serial Number	KMT0D111K01060192

Note for External Appearance

The body is partly rusty and damaged



Upper Structure

Blade Tilt Cylinder	No oil leak	
	Left	Right
Lift Arm Cylinder	No oil leak	No oil leak
Blade Angle Cylinder	No oil leak	No oil leak
Travel Motor	No oil leak	No oil leak

Note for Upper Structure

The blade has some dents



Undercarriage

	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Shoe Link	OK	OK
Sprocket	OK	OK
Track Roller	OK	OK
Upper Roller	OK	OK
Pin Bush	OK	OK

Note for Operating Component

- ROPS
- Air conditioner



Note for Undercarriage



Engine

Model	SAA4D95LE
Serial Number	505015
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Engine

EPA



Admin. No. 3000011665

*This report is only for your reference. We are not responsible for the actual condition of checked item.