

Inspection Report

Inspection Date: 2024/10/17

Excavators

General Information		
Maker	YANMAR	
Model Number	VIO45-6	
Year	2015	
Hour (h)	3732 Meter	Working
Serial Number	62447	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	Flay
Boom	Left	No	No	No
Boom	Right	N/A	N/A	NO
	Arm	No	No	No
Bucket No No		No	Small	
Bucket Siz	ze (mm)	590		

Undercarriage

ondercarnage		
Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	350	350
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	NG	NG
Shoe Link	ОК	ОК

EngineModel4TNV88-ZPBVSerial NumberT9343Engine Oil LeakNo oil leakEngine Oil GaugeOKRadiatorOKRabiatorNormalBlow-byNoEngine SoundOKHydraulic PumpNo oil leakWater PumpNo oil leakOil CoolerNo oil leakMoti leakNo oil leakMulti LeverNo oil leak


Options	
- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Note for External Appearance



Note for Upper Structure	

Note for Undercarriage - Oil oozing from 2 left lower rollers - Oil oozing from 1 right lower roller



Note for Engine		
	Admin No.	3000065132

*This report is only for your reference. We are not responsible for the actual condition of checked item.