



Inspection Report

Inspection Date: 6/28/2016

Excavator

General Information

Maker	SUMITOMO
Model Number	SH75X-3UC
Year	2007
Hour (h)	4294
Serial Number	6[REDACTED]

Note for External Appearance

- The upper part of the blade is bent
- The edge of the front frame has a dent



Upper Structure

Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	700
Swing	Backlash and play

Note for Upper Structure

- Equipped with multi lever and arm crane
- The bucket pin has a slight play
- The arm has a dent



Note for Undercarriage

Steel shoes + rubber pads



Undercarriage

Swivel Joint	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Operating Component



Engine

Model	4TNE98-SH
Serial Number	35056
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Engine

- Oil oozing from the connection between the engine and pump
- Fuel oil oozing from the connection of the fuel pump

