



# Inspection Report


Inspection Date: 2018/03/14

## Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-406		
Year	2009		
Hour (h)	3738	Meter	Working
Serial Number	10008		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		540		


Note for External Appearance
- The body is partly repainted - The right side cover is slightly deformed


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The offset has a play


Note for Undercarriage
Oil oozing from the left lower rollers


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Lot No ARA013-0034 Admin No. 2018030690