



Inspection Report


Inspection Date: 2017/10/10

Excavators


General Information			
Maker	YANMAR		
Model Number	B6-6		
Year	2005		
Hour (h)	2843	Meter	Working
Serial Number	60573B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		610		


Note for External Appearance
The body has some dents and are repainted


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The inside of the arm has some dents
- The blade is partly deformed


Note for Undercarriage
- The rubber shoes have deteriorated over time
- Oil oozing from the right reduction drive
- Oil oozing from one of the right lower rollers


Engine	
Model	4TNV88-P
Serial Number	25349
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017100809