



# Inspection Report

Inspection Date: 2018/02/27

## Roller

### General Information

Maker	SAKAI
Model Number	T2
Year	1999
Hour (h)	2802
Serial Number	32602

### Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Note for External Appearance



### Note for Undercarriage

- Tire size: 14/70-20
- The right front tire is partly chipped
- The left rear tire is partly damaged
- Oil leak from the steering cylinder



### Note for Operating Component

- The seat is partly fixed
- The sprayer works without problems
- Mileage: 8639km



### Note for Engine

Oil oozing from around the injection pump



Lot No ARA013-0055

Admin. No. 2018020541

\*This report is only for your reference. We are not responsible for the actual condition of checked item.