



# Inspection Report

Inspection Date: 2026/07/18

## Excavators

### General Information

|               |                   |       |         |
|---------------|-------------------|-------|---------|
| #ERROR!       | HITACHI           |       |         |
| Model Number  | ZX120-3           |       |         |
| Year          | 2013              |       |         |
| Hour (h)      | 8369              | Meter | Working |
| Serial Number | HCM1R100C00092999 |       |         |

### Options

|              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Blade      | - Pippings        |

### Upper Structure

|                  |       | Cylinder   |              | Play  |
|------------------|-------|------------|--------------|-------|
|                  |       | Oil Leak   | Scratch/Rust |       |
| Boom             | Left  | Oil oozing | No           | Small |
|                  | Right | Oil oozing | No           |       |
| Arm              |       | Oil oozing | No           | Small |
| Bucket           |       | No         | No           | Small |
| Bucket Size (mm) |       | 880        |              |       |

### Note for External Appearance

- Repainted
- The overall body has some scratches and rust



### Undercarriage

| Shoe Type       | Steel       |       |
|-----------------|-------------|-------|
| Swing Circle    | No oil leak |       |
|                 | Left        | Right |
| Shoe Width (mm) | 500         | 500   |
| Idler           | OK          | OK    |
| Sprocket        | OK          | OK    |
| Pin Bush        | OK          | OK    |
| Upper Roller    | OK          | OK    |
| Track Roller    | OK          | OK    |
| Shoe Link       | OK          | OK    |

### Note for Upper Structure



### Note for Undercarriage



### Engine

|                  |                |
|------------------|----------------|
| Model            | AJ-4JJ1XYSA-03 |
| Serial Number    | 161432         |
| Engine Oil Leak  | No oil leak    |
| Engine Oil Gauge | OK             |
| Radiator         | OK             |
| Exhaust Color    | Normal         |
| Blow-by          | No             |
| Engine Sound     | OK             |
| Hydraulic Pump   | No oil leak    |
| Water Pump       | No water leak  |
| Oil Cooler       | No oil leak    |
| Motor            | No oil leak    |
| Multi Lever      | No oil leak    |

### Note for Operating Component



### Note for Engine



Admin No. 3000087732

\*This report is only for your reference. We are not responsible for the actual condition of checked item.