



# Inspection Report

Inspection Date: 2024/12/11

## Excavators

### General Information

Maker	YANMAR		
Model Number	SV05B		
Year	2015		
Hour (h)	797	Meter	Working
Serial Number	03846		

### Options


- Blade	
---------	--

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	280			

### Note for External Appearance

- The covers have some rust and scratches.




### Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	150	150	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

### Note for Upper Structure

- The bucket bottom has some dents  
- Oil oozing from the swivel joint



### Note for Undercarriage



### Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

### Note for Operating Component

- The seat is torn



### Note for Engine



Admin No. 3000067415