



Inspection Report

Inspection Date: 2018/06/26

Excavators

General Information

Maker	HITACHI		
Model Number	ZX120-E		
Year	2007		
Hour (h)	4789	Meter	Working
Serial Number	HCM1S900L0073285		

Options

- CAB
- Multilever
- EPA
- Speed changer
- Air conditioner
- Pipings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	No	No	
	Arm	No	No	Big
	Bucket	No	No	Big
	Bucket Size (mm)	880		

Note for External Appearance

Repainted



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure

2 sides of the arm were reinforced



Note for Undercarriage

- Oil oozing from 2 of the right lower rollers
- The rubber pads are partly worn



Engine

Model	CC-4BG1 TCG
Serial Number	4BG1-938472
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

Fuel leak from the fuel filter



Admin No. 2018061639