



# Inspection Report


Inspection Date: 2022/11/11

## Excavators


General Information			
Maker	KOMATSU		
Model Number	PC128US-2E1		
Year	2006		
Hour (h)	8580	Meter	Working
Serial Number	KMTPC039P01010793		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Pipings
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	Oil oozing	No	
Arm		No	No	Small
Bucket		No	Yes	Big
Bucket Size (mm)		825		


Note for External Appearance


Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage


Engine	
Model	SAA4D95LE-3
Serial Number	112675
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
- The seat is torn


Note for Engine


Admin No. 3000043662