



Inspection Report

Inspection Date: 2025/12/11

Excavators

General Information	
Maker	KOMATSU
Model Number	PC20UU-5
Year	2012
Hour (h)	2550
Meter	Working
Serial Number	KMTPC225P04015243

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure			
		Cylinder	
		Oil Leak	Scratch/Rust
Boom	Left	No	No
	Right	N/A	N/A
Arm		No	No
Bucket		No	No
Bucket Size (mm)		420	

Note for External Appearance	
- Repainted	
- The body has scratches and rust	



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	



Engine	
Model	3D76E-6NDA
Serial Number	06932
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component	



Note for Engine	



Admin No. 3000079528

*This report is only for your reference. We are not responsible for the actual condition of checked item.