



Inspection Report

Inspection Date: 2018/07/23

Generator

General Information

Maker	DENYO
Model Number	DCA-25USI
Year	2004
Hour (h)	12563
Serial Number	3751188

Note for External Appearance

The meter is broken

Engine

Model	AA-4LE2
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	Unchecked
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Admin. No. 2018070815

*This report is only for your reference. We are not responsible for the actual condition of checked item.