



Inspection Report

Inspection Date: 2019/07/16

Excavators

General Information

Maker	YANMAR		
Model Number	ViO35-5		
Year	2007		
Hour (h)	5263	Meter	Working
Serial Number	50875B		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Piping |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		Oil oozing	No	Big
Bucket Size (mm)		630		

Note for External Appearance

The blade has some dents



Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	NG
Shoe Link	OK	OK

Note for Upper Structure

The boom gradually drops by itself



Note for Undercarriage

- Oil oozing from around the right travel motor
- Oil oozing from each one of the right and left lower rollers



Engine

Model	3TNV88-Q
Serial Number	54988
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The armrests are broken
- The seat is partly torn



Note for Engine

The engine has been fixed



Admin No. 2019070581