



Inspection Report

Inspection Date: 2024/07/31

Excavators

General Information

Maker	YANMAR		
Model Number	Vio70-3A		
Year	2011		
Hour (h)	4095	Meter	Working
Serial Number	36273B		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	Scratch	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	620			

Note for External Appearance

- The covers have rust and scratches




Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

- The bucket bottom has some dents



Note for Undercarriage

- The rubber pads are cracked
- Oil oozing from one of the right lower rollers



Engine

Model	4TNV98-ZWBV
Serial Number	J7466
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

- Slight blow-by



Admin No. 3000061614