



Inspection Report

Inspection Date: 2023/03/01

Truck

General Information

Maker	HINO
Model Number	FD1JLD
Year	
Mileage (km)	304960
Serial Number	10927

Note for External Appearance

- The truck bed is deformed
- The body has some scratches and dents

Engine

Model	J08C
Serial Number	
Engine Oil Leak	No
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- The operation of the radio control has not been checked
- The warning lamp is missing
- The seat is torn

Note for Engine

- F6

Admin. No. 3000046692

*This report is only for your reference. We are not responsible for the actual condition of checked item.