



# Inspection Report

Inspection Date:

## Asphalt Finisher

### General Information

<b>Maker</b>	SUMITOMO
<b>Model Number</b>	HA25W-2 / 4WD
<b>Year</b>	1999
<b>Hour (h)</b>	6720
<b>Serial Number</b>	HA25W-5091

### Note for External Appearance

- Paving width: 1400-2500mm  
- Traveling condition (front / back travel) was checked  
- Operating condition of the vibrator, hoppers, screeds, and feeder are ok

### Engine

<b>Model</b>	V2203-KB
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

### Note for Engine

### Other Information

Admin. No. 3000050008

\*This report is only for your reference. We are not responsible for the actual condition of checked item.