



Inspection Report

Inspection Date: 2024/07/05

Excavators

General Information

Maker	KUBOTA		
Model Number	U-20-3S		
Year	2011		
Hour (h)	3080	Meter	#N/A
Serial Number	13376		

Options


- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	400			

Note for External Appearance

- Repainted
- Oil leak from the bottom



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


Note for Upper Structure

--



Note for Undercarriage

- The travel motor covers are detached
- Oil leak from the left travel motor



Engine

Model	
Serial Number	BS2056
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

--



Admin No. 3000060646