



Inspection Report

Inspection Date: 2019/03/15


Excavators

General Information			
Maker	AIRMAN		
Model Number	AX27U-5		
Year	2009		
Hour (h)	1421	Meter	Working
Serial Number	1NDA0200083		

Options	
- CNP	
- Multilever	
- Blade	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		430		

Note for External Appearance



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage




Engine	
Model	3KNSA
Serial Number	3TNV88-BSHBB
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

The hydraulic hoses have deteriorated



Admin No. 2019030197