



# Inspection Report

Inspection Date: 2021/10/09

## Welder

### General Information

<b>Maker</b>	DENYO
<b>Model Number</b>	GAW-185ES
<b>Year</b>	2010
<b>Hour (h)</b>	
<b>Serial Number</b>	5639451

### Engine

<b>Model</b>	EH36DS
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	Unchecked
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	Unchecked
<b>Water Pump</b>	Unchecked

### Note for External Appearance

### Note for Control Panel

- The monitor is broken

### Note for Engine

It does not generate power

Admin. No. 3000035685

\*This report is only for your reference. We are not responsible for the actual condition of checked item.