

# **Inspection Report**

## **Excavator**

General Information		
Maker	SUMITOMO	
Model Number	SH125X-3	
Year	2002	
Hour (h)	6918	
Serial Number	125X3-14**	

Upper Structure	
Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	800
Swing	Unchecked

### Undercarriage

Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	ОК	ОК

Engine		
Model	BB-4BG1T	
Serial Number		
Engine Oil Leak	Oil oozing	
Engine Oil Gauge	Oil shortage	
Radiator	Not enough cooling water	
Exhaust Color	Normal	
Blow-by	No	
Engine Sound	ОК	
Hydraulic Pump	Oil leak	
Water Pump	No water leak	
Oil Cooler	No oil leak	
Motor	No oil leak	
Multi Lever	No oil leak	

### Note for External Appearance

Overall dents



### Note for Upper Structure

Oil leak and machine does not have enough power



### Note for Undercarriage

Due to one of crawler unworkable, machine cannot move forward

### Note for Operating Component

Drink holder broken



# Note for Engine



\*This report is only for your reference. We are not responsible for the actual condition of checked item.