



Inspection Report


Inspection Date: 2017/10/10

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO30-5		
Year	2007		
Hour (h)	2555	Meter	Working
Serial Number	51759B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		470		


Note for External Appearance


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The inside of the arm has some dents


Note for Undercarriage


Engine	
Model	3TNV82A-N
Serial Number	49645
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017100772