



Inspection Report

Inspection Date: 2024/07/13

Excavators

General Information

| | | | |
|----------------------|--------|--------------|---------|
| Maker | KUBOTA | | |
| Model Number | RX-203 | | |
| Year | 2010 | | |
| Hour (h) | 3384 | Meter | Working |
| Serial Number | 10761 | | |

Options

| | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | 400 | | | |

Note for External Appearance

| |
|--------------------|
| - Repainted |
| - No caution plate |



Undercarriage

| Shoe Type | Rubber | |
|------------------------|-------------|-------|
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 250 | 250 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Upper Structure



Note for Undercarriage



Engine

| | |
|-------------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | Oil oozing |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |


Note for Operating Component

| |
|--------------------|
| - The seat is torn |
|--------------------|



Note for Engine

| |
|--|
| - The battery is flat; the condition was checked the with the booster cables |
|--|



Admin No. 3000061032