



Inspection Report

Inspection Date: 2024/11/15

Generator

General Information

Maker	HOKUETSU
Model Number	PDW300AS
Year	2000
Hour (h)	6466
Serial Number	614-230138

Note for External Appearance

- Repainted
- The cover is rusty and has some scratches
- The cover is deformed

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Oil shortage
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	Not enough cooling water
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

- The dynamo is broken (it can travel only when the battery is connected)
- The engine stalls when the battery is not connected

Admin. No. 3000063530

*This report is only for your reference. We are not responsible for the actual condition of checked item.